

## Valley County Bridges and Sufficiency Ratings

Master Key No.	Road	Milepost	Feature Crossed	Inspection Date	Element	Sufficiency Rating
28635	SMITH FERRY ROAD	105.938	N.FK.PAYETTE RIVER	08/11/07	Bridge	46.6
28671	GOLD FORK ROAD	106.882	KENNALLY CREEK	08/19/07	Bridge	59.9
33615	WARREN-PROFILE GAP	143.992	SOUTH FORK SALMON RIVER	09/10/07	Timber Deck	60.6
20095	STC 3906; WARREN WAGON	005.845	DEAD HORSE CREEK	08/11/07	Timber Deck Bridge	62.1
28595	SCHELIN LANE	101.211	LAKE FORK CREEK	08/11/07	Bridge	64.9
28640	EAST LAKE FORK RD	103.566	LAKE FORK CREEK	08/11/07	Bridge	66.0
28655	CO.RD;PLNG#0013	106.223	N.FK.PAYETTE R(N.BEACH)	08/10/06	Bridge	70.7
20165	EAST FORK ROAD	036.277	E.FK. OF S.FK.SALMON RVR	09/07/07	Bridge	73.3
28580	HORSETHIEF RD	111.923	BIG CREEK	09/27/06	Bridge	75.6
33835	DEADWOOD ROAD	113.219	DEADWOOD RIVER	08/16/06	Bridge	75.7
33600	WARREN-PROFILE GAP	139.024	PILOT CREEK	09/10/07	Bridge	76.8
20155	SOUTH FORK RD	035.100	SECESH RIVER	09/27/06	Bridge	77.0
20160	EAST FORK RD	035.953	S.FK.SALMON RIVER	09/27/06	Timber Deck Bridge	77.0
20150	LICK CREEK RD	032.100	ZENA CREEK	09/27/06	Bridge	79.0
28610	GOLD DUST ROAD	100.467	BIG CREEK	08/11/07	Bridge	79.2
20075	STC3899;ROSEBERRY	002.530	LAKE FORK CREEK	08/19/07	Bridge	79.4
33605	WARREN-PROFILE GAP	140.712	UPPER ELK CREEK	09/10/07	Bridge	80.3
33610	WARREN-PROFILE GAP	142.062	LOWER ELK CREEK	09/10/07	Bridge	80.3
28660	ELO ROAD	114.356	LAKE FORK CREEK	08/19/07	Bridge	80.6
28566	CO. RD.;PLNG #0126	102.625	ROUND VALLEY CREEK	08/11/07	Bridge	81.9
20090	STC 3904	023.435	S.FK.SALMON RIVER	09/27/06	Conc Bridge	87.2
20105	STC 3906	015.985	N.FK.PAYETTE RIVER	08/12/06	Bridge	88.2
20110	STC 3906	017.460	TWENTY MILE CREEK	08/12/06	Bridge	88.2
28629	PADDY FLAT ROAD	103.135	BOULDER CREEK	08/19/07	Steel Culvert	89.8
28590	SMYLIE LANE	101.023	N.FK.PAYETTE RIVER	08/19/07	Bridge	89.9
28620	CARBARTON ROAD	102.017	N.FK.PAYETTE RIVER	08/11/07	Bridge	90.0
33860	STC3895;YELLOWPINE	103.344	LUNCH CREEK	08/17/06	Bridge	90.0
33865	STC3895;YELLOWPINE	107.749	TROUT CREEK	08/17/06	Bridge	90.0
20170	EAST FORK RD	050.750	E.FK. OF S.FK.SALMON RVR	09/27/06	Bridge	90.5
28646	STC3895;KNX YLWPNE	121.248	RIORDAN CREEK	09/07/07	Bridge	92.2
20100	STC 3906	010.085	FISHER CREEK	08/12/06	Conc Bridge	92.3
33870	STC3895;YELLOWPINE	113.288	JOHNSON CREEK	08/17/06	Bridge	93.0
28570	NISULA ROAD	100.428	MUD CREEK	08/11/07	Steel Culvert	96.0
20068	ROSEBERRY ROAD	000.060	WILLOW CREEK	08/19/07	Bridge	96.9
20071	COUNTY ROAD	001.357	BOULDER CREEK	08/10/06	Misc Culvert	97.9
28631	FARM TO MARKET RD	107.094	BOULDER CREEK	08/10/06	Bridge	97.9
20080	STC 3899	025.095	CASCADE RESERVOIR	08/11/07	Bridge	98.4
28568	ROSEBERRY ROAD	100.917	MUD CREEK	08/19/07	Bridge	99.0
20086	STC 3899; NORWOOD	028.390	MUD CREEK	08/19/07	Bridge	99.0
28545	HANSEN LANE	102.354	GOLD FORK CREEK	08/19/07	Bridge	100.0

BRKEY	STRUCNAME	ROUTE	FEATURES	MTCE RECOMMENDATION	INSPDATE	PRIORITY	ELEMENT	SUFF_RATE	POSTED	TYPE 3	TYPE 3S2	TYPE 3-3	MAX AXLE
20068	X993430 0.06	ROSEBERRY ROAD	WILLOW CREEK	Install OM-3 hazard markers.	8/19/2007	High	Bridge	96.9	A				
20075	93899A 2.53	STC 3899, ROSEBERRY	LAKE FORK CREEK	Install new expansion joint material at center of bridge and abutments. Repair concrete deck and backwall at that point. Repair concrete curbs where damaged. Monitor rusting and pitting of steel piles of center pier and paint as required. Remove debris from bearing areas. Place thin concrete sealant on deck surface to prevent further deterioration. Paint and/or cover rebar at NE approach. Replace connection of top rail to posts. Monitor spalling of girder #4, span #1 at bearing. Repair broken post and bent railing @ NW corner. Repair post #10 on N side.	8/19/2007	High Medium Medium Low Medium Medium Medium Low Medium	Compression Joint Seal Bare Concrete Deck Bridge Paint Stl Sub Pile Moveable Bearing Bare Concrete Deck Bare Concrete Deck Metal Rail Coated P/S Conc Open Girder Metal Rail Coated	79.4	A				
20080	93899A 25.10	STC 3899	CASCADE RESERVOIR	Place backfill at approach shoulders. Remove gravel on rail post pillars. Repair undermining of NW wingwall. Remove excess sand and gravel from deck and expansion joints. Replace broken and missing guardrail posts.	8/11/2007	Medium Low Medium Medium Medium	Bridge Metal Rail Coated Bridge Bridge Bridge	98.4	A				
20086	93899A 28.39	STC 3899, NORWOOD	MUD CREEK	Remove dirt & gravel from flanges. Repair/replace end sections at NE & SE approaches. Remove gravel from bottom chord of rail truss.	8/19/2007	Medium High Medium	Paint Stl Opn Girder Metal Rail Coated Bridge	99.0	A				
20095	93906A 5.85	STC 3906 WARREN WAGON RD	DEAD HORSE CREEK	Repair deck hold down bolts Replace rail along east side including post #3. Secure west rail to posts.	8/11/2007	Low High	Timber Deck/AC Ovl Bridge	62.1	P	24	40	45	9
20165	X993430 36.31	EAST FORK ROAD	E.FK. OF S.FK. SALMON RIVER	Remove asphalt wearing surface and install new surface. Repair damaged curbs as required. Paint exposed rebar. Repair damaged signs. Replace burnt portions of railing, posts and curbs on span #1 and span #4. Clean and paint girders, diaphragm, and x-bracing. Place rip rap on top around exposed footings.	9/7/2007	Low Low Low Low High Medium Low	Bridge Bridge RC Wingwall Bridge Timb Bridge Railing Paint Stl Opn Girder R/Conc Pier Wall	73.3	A				
28545	X993430 0.01	HANSEN LANE	GOLD FORK CREEK	Repair bridge rail and replace broken or missing posts at SE corner.	8/19/2007	Medium	Conc Bridge Railing	100.0	A				
28566	X993430 102.63	CO.RD.:PLNG #0126	ROUND VALLEY CREEK	Repair damaged guardrail and replace Place thin sealant on deck. Replace OM-3 hazard markers at SW and NE corners	8/11/2007	High Low High	Bridge Bridge Bridge	81.9	A				
28568	X993430 100.92	ROSEBERRY ROAD	MUD CREEK	Remove dirt & gravel from flange.	8/19/2007	Medium	Paint Stl Opn Girder	99.0	A				
28570	X993430 0.43	NISULA ROAD	MUD CREEK	Remove sand and dirt from culverts and remove tree from #3 culvert. Remove down tree from #2 & #3 inlet. Place hazard markers. Raise fence above culverts on south end.	8/11/2007	High Medium Low	Steel Culvert Bridge Bridge	96.0	A				
28590	X993430 1.06	SMYLIE LANE	N.FK. PAYETTE RIVER	Install new joint material in expansion joints. Remove dirt and gravel from bearing area on East abutment Seal underneath side of girders Re-attach x-bracing on pier #2. Attach rail at SE corner to 2nd post.	8/19/2007	Medium Medium Low Medium Medium	Compressn Joint Seal R/Conc Abutment P/S Conc Open Girder Paint Stl Column Metal Rail Coated	89.9	A				
28595	X993430 1.25	CHELINE LANE	LAKE FORK CREEK	Repair edges of concrete girders. Seal underneath surfaces. Remove obstruction from stream. Clean debris from bridge rail post supports.	8/11/2007	Low Low Medium Low	P/S Conc Open Girder P/S Conc Open Girder Bridge Metal Rail Coated	64.9	A				
28610	X993430 1.45	GOLD DUST ROAD	BIG CREEK	Paint and/or cover exposed rebar on single tee stems and flanges on N bearing and at side connections. Seal edges of concrete single tees to prevent further deterioration of edges. Seal and/or rehabilitate edges of concrete deck to prevent further deterioration of edges.	8/11/2007	Medium Medium Medium	P/S Conc Open Girder P/S Conc Open Girder Unp Conc Deck/AC Ovl	79.2	A				
28620	X993430 1.77	CARBARTON ROAD	N.FK. PAYETTE RIVER	Repair damaged guard rail at both approaches. Repair damaged bridge railing at NE corner. Repair spalling at concrete diaphragms. ***See supplementary inspection report done 10/94*** Replace broken post at NE guardrail and split guardrail posts.	8/11/2007	Medium Low Low Medium	Bridge Metal Rail Coated P/S Conc Open Girder Bridge	90.0	A				
28629	X993430 103.14	PADDY FLAT ROAD	BOULDER CREEK	Remove rock & debris from culvert inlets.	8/19/2007	Low	Steel Culvert	89.8	A				
28635	X993430 3.28	SMITH FERRY ROAD	N.FK. PAYETTE RIVER	Paint I-beam posts for railing. Repair damaged bridge railing. Repair girder #2, span #2 at pier #1. Replace material at curb lines where missing Replace and/or repair concrete curbs. Repair diaphragm between girder #2 and #3 @ pier cap #5 to cover exposed reinforcement.	8/11/2007	Low Low Low Medium Low Medium	Metal Rail Coated Metal Rail Coated R/Conc Open Girder Compressn Joint Seal Bridge R/Conc Open Girder	46.6	A				
28640	X993430 3.68	EAST LAKE FORK ROAD	LAKE FORK CREEK	Install new expansion joint material and paint side plates. Patch or paint areas where rebar is exposed on underneath sides. Paint steel girders at ends. Repair terminal sections of bridge rail at all corners.	8/11/2007	Medium Medium Low Low	Compressn Joint Seal Unp Conc Slab/AC Ovl Paint Stl Opn Girder Metal Rail Coated	66.0	A				
28646	98956A 121.25	STC 3895; KNX YLWPNE	RIORDAN CREEK	One Lane Bridge' signs may be replaced with 'One Lane Bridge for Trucks and Buses.' Install OM-3 hazard markers at SW corner	9/7/2007	Low Medium	Bridge Bridge	92.2	A				

BRKEY	STRUCNAME	ROUTE	FEATURES	MTCE RECOMMENDATION	INSPDATE	PRIORITY	ELEMENT	SUFF_RATE	POSTED	TYPE 3	TYPE 3S2	TYPE 3-3	MAX AXLE
28660	X993430 10.18	ELO ROAD	LAKE FORK CREEK	Repair spalled areas of exterior girder flanges. Repair damaged portions of bridge railing. Install new concrete sealant surface across bridge. Install new asphalt approaches at abutments and bring to same elevation as bridge deck. Seal single tees and monitor cracking. Remove grass from around all OM-3 hazard markers. Repair NE marker	8/19/2007	Low Low Low Medium Medium High	P/S Conc Open Girder Metal Rail Coated Bridge Bridge P/S Conc Open Girder Bridge	80.6	A				
28671	X993430 106.88	GOLD FORK ROAD	KENALLY CREEK	Repair damaged curb Seal exterior girder. Replace expansion joint material at center pier. Clean off bearing area @ center pier. Tighten all bottom rods. Replace missing nuts. Reattach rod #2, span #2.	8/19/2007	Low Medium High Medium High	Bridge Timber Open Girder Compressn Joint Seal Fixed Bearing Timber Open Girder	59.9	A				
33600	X993430 139.02	WARREN-PROFILE GAP	PILOT CREEK	Install 'One Lane Bridge' signs on both approaches.	9/10/2007	Medium	Bridge	76.8	A				
33605	X993430 140.71	WARREN-PROFILE GAP	UPPER ELK CREEK	Install 'Single Lane Truck and Busses' signs on both approaches.	9/10/2007	Medium	Bridge	80.3	A				
33610	X993430 142.06	WARREN-PROFILE GAP	LOWER ELK CREEK	Install 'Single Lane Truck and Busses' signs on both approaches.	9/10/2007	Medium	Bridge	80.3	A				
33615	X993430 143.99	WARREN-PROFILE GAP	SOUTH FORK SALMON RIVER	Install 'One Lane Bridge' signs on both approaches.	9/10/2007	High	Timber Deck	60.6	A				
33620	X993430 145.44	WARREN-PROFILE GAP	PONY CREEK		9/10/2007			91.9					
20071	X993430 1.36	ROSEBERRY ROAD	BOULDER CREEK	Install additional posts for guardrail. Remove excess sand from east culvert entrance and exit areas. Remove barb wire from upstream side. Remove brush that is growing between culvert and headwall. Repair broken posts in railing.	8/10/2006	Low High Medium High	Metal Rail Coated Misc. Culvert Misc. Culvert Metal Rail Coated	97.9	A				
20090	93904A 23.44	STC 3904	S.FK. SALMON RIVER	Paint rusty plates at ends. Install OM-3 hazard markers at SW, NE, and NW corners.	9/27/2006	Low Medium	Unp Conc Deck/AC Ovl Bridge	87.2	A				
20100	93906A 10.09	STC 3906 WARREN WAGON RD	FISHER CREEK	Seal deck to stop leaching through cracks. Repair Damaged areas of approach railing. Repair bridge rails at ends. Turn hazard marker at SW corner so that it faces traffic.	8/12/2006	Medium Low Low Medium	Bare Concrete Deck Bridge Metal Rail Coated Bridge	88.2	A				
20105	93906A 16.00	STC 3906 WARREN WAGON RD	N.FK. PAYETTE RIVER	Repair damaged guardrail at southeast corner. Repair bridge rail at northeast corner. Install better joint material at sidewalk expansion joints to prevent deterioration on underneath side. Repair spalled areas of bridge rail. Install thin concrete sealant (Silane). Repair deterioration of girders at diaphragm attachments.	8/12/2006	Medium Medium Medium Low Low Low	Bare Concrete Deck Conc Bridge Railing Bridge Conc Bridge Railing Bare Concrete Deck P/S Conc Open Girder	88.2	A				
20110	93906A 17.47	STC 3906 WARREN WAGON RD	TWENTY MILE CREEK	Install thin concrete sealant (Silane) across bridge deck. Repair broken rails at all corners. Repair damaged guardrail. Clean bearing area at SE corner. Extend drains past bottom of girders. Turn OM-3 hazard marker @ SW corner toward traffic.	8/12/2006	Low Medium Low Medium Medium Medium	Bare Concrete Deck Bare Concrete Deck Bridge Elastomeric Bearing Bare Concrete Deck Bridge	88.2	A				
20150	X993430 32.10	LICK CREEK ROAD	ZENA CREEK	Remove weeds from in front of hazard markers.	9/27/2006	High	Bridge	79.0	A				
20155	X993430 35.10	SOUTH FORK ROAD	SECESH RIVER	Repair damaged hazard marker. Replace asphalt wearing surface. Schedule entire steel superstructure to be painted. Cover exposed reinforcement in east abutment. Repair bridge at northeast corner. Replace grout around bearing plates. Replace broken and missing rail on right side. Also cracked rail on left side same location.	9/27/2006	Medium Medium Low Low Medium Low High	Bridge Timber Deck/AC Ovl Paint Stl Opn Girder R/Conc Abutment Timb Bridge Railing Fixed Bearing Timb Bridge Railing	77.0	A				
20160	X993430 35.95	EAST FORK ROAD	S.FK. SALMON RIVER	Install new wearing surface. Paint rusting girders, diaphragms and bearings. Clean bearing areas. Repair damaged areas of bridge rail and curb. Remove sand and gravel along deck edges. Open drainage areas. Install OM-3 hazard marker at abutment #1, right side.	9/27/2006	Medium Low Low Low Medium Medium	Timber Deck/AC Ovl Paint Stl Opn Girder Paint Stl Opn Girder Timb Bridge Railing Timber Deck/AC Ovl Bridge	77.0	A				
20170	X993430 50.75	EAST FORK ROAD	E.FK. OF S.FK. SALMON RIVER	Place concrete sealant coat on deck Paint rails and posts as required. Clean deck drains. Install hazard markers at northwest corner.	9/27/2006	Low Low Low High	Bare Concrete Deck Metal Rail Coated Bare Concrete Deck Bridge	90.5	A				
28561	X993430 10.4.79	FARM TO MARKET ROAD	WILLOW CREEK		8/10/2006			96.9					
28580	X993430 0.84	HORSETHIEF ROAD	BIG CREEK	Place additional riprap as required along both abutments #1 and #2.	9/27/2006	Low	Bridge	75.6	A				
28628	X993430 101.86	SPINK LANE	BOULDER CREEK		8/10/2006			87.3					
28631	X993430 107.10	FARM TO MARKET ROAD	BOULDER CREEK	Install additional guard rail posts across the structure. Remove vegetation growth at joint between culvert and headwall. Remove excess sand from channel inside culverts. Tighten bolts that show water leakage.	8/10/2006	Low Low Low Low	Metal Rail Coated Misc. Culvert Bridge Misc. Culvert	97.9	A				
28655	X993430 6.38	CO.RD;PLNG#0013	N.FK. PAYETTE RIVER(N.BEACH)	Repair concrete curbs. Repair expansion joints. Paint railing and posts on bridge railings. Clean bearing area at center pier. Open deck drains and remove excess sand and gravel from edges of deck. Install additional drain extensions. Place backfill at SE and SW wingwalls.	8/10/2006	Low Medium Low Low High Low Low	Bridge Compressn Joint Seal Metal Rail Coated R/Conc Open Girder Bare Concrete Deck Bare Concrete Deck Bridge	70.7	P	24	37	45	9

BRKEY	STRUCNAME	ROUTE	FEATURES	MTCE RECOMMENDATION	INSPDATE	PRIORITY	ELEMENT	SUFF_RATE	POSTED	TYPE 3	TYPE 3S2	TYPE 3-3	MAX AXLE
28666	X993430 115.79	ELO ROAD	LAKE FORK CANAL		8/10/2006			96.2					
33800	X993430 100.11	DEER CREEK ROAD	BEAR VALLEY CREEK		10/19/2006				A				
33805	X993430 109.77	CLEAR CREEK ROAD	CACHE CREEK		10/19/2006				A				
33810	X993430 109.64	LANDMARK/STANLEY RD.	ELK CREEK #1		10/18/2006				A				
33815	X993430 109.68	LANDMARK/STANLEY RD.	ELK CREEK #2		10/18/2006				A				
33820	X993430 115.18	LANDMARK/STANLEY RD.	BEAR VALLEY CREEK		10/18/2006				A				
33835	X993430 113.22	DEADWOOD ROAD	DEADWOOD RIVER	Install 'Single Lane All Vehicles' signs on both approaches.	8/16/2006	High	Bridge	75.7	P	24	32	40	
33840	X993430 114.71	DEADWOOD ROAD	DEADWOOD RIVER	Install "One lane bridge" signs on both approaches.	8/16/2006	High	Bridge		A				
33845	X993430 117.47	DEADWOOD ROAD	DEER CREEK		8/16/2006				P	24	36	43	
33850	X993430 135.59	LANDMARK/STANLEY RD	JOHNSON CREEK		8/15/2006				A				
33855	X993430 136.61	LANDMARK/STANLEY RD	ROCK CREEK		8/15/2006				A				
33860	93895A 103.34	STC3895;YELLOW PINE	LUNCH CREEK	Install 'Single Lane for Trucks and Busses' signs on both approaches.	8/17/2006	High	Bridge	90.0	A				
33865	93895A 107.75	STC3895;YELLOW PINE	TROUT CREEK	Repair the settled asphalt approaches at both ends of the bridge.	8/17/2006	Medium	Bridge	90.0	A				
33870	93895A 113.29	STC3895;YELLOW PINE	JOHNSON CREEK	Replace the broken bridge marker post on the North/West corner of the bridge.	8/17/2006	Medium	Bridge						